

info@naturaplaygrounds.com.au Log Water Channel Carved Manufacturers Information | PN1231

Update 01/03/2023

naturaplaygrounds.com.au



Installation

Footing quantities and From ground level

| depths | Item | Qty | Hole Diameter | ŀ |
|--------|-------|-----|---------------|---|
| | Posts | 2 | 300mm | |



Material Specifications

| Log | Ironbark timber, river rocks and resin |
|----------|----------------------------------------|
| Footings | Stainless Steel |
| Fixings | Stainless Steel |

Equipment Specifications

| Free Height of Fall | Not required |
|-------------------------|---------------------------|
| Fall Zone Size | Not required |
| Activity Space Required | Allow 1m around equipment |
| Highest Point | Dependant on installation |

Other Required Information

| Spare Parts | Available to order |
|---------------|-------------------------------------|
| Largest Part | Log channel |
| Heaviest Part | Log Channel 21-40kg Two Person Lift |


Standards


AS 4685 2021 Series

Applications

| Age Group | 3 years + |
|----------------------|--------------------------------------------------------------------------------------------------------|
| Supervision Level | Young children should be supervised and inappropriate activities discouraged |
| Playspaces | Public parks, schools, early childhood centres commercial play areas |
| Environment | Shade preferred for user comfort and protection. Salt air environments may reduce life of steel. |
| Vandalism Resistance | Low susceptibility |

Product Dimensions





Inspection Notes

All inspections and maintenance to be carried out by competent people with the appropriate knowledge, experience and authority.

Inspection Frequencies

These are a guide only - local risk factors such as heavy usage, nearness to coast, and vandalism patterns need to be taken into account.

Routine Visual Inspection - Daily

Operational Inspectio

Check for breakages, loose fittings and debris. Where safety issues are identified, quarantine until repaired.

RVI plus:-Check for wear in mov bearings, chains and Check security of fixin

Maintenance

In areas of high exposure to sun, wind and rain more frequent treatments may be necessary. Note: Ensure all replacement parts conform with manufacturers original specifications Note: In heavy use environment, more frequent inspection regime recommended Note: Quarantine equipment during installation, inspection & maintenance

naturaplaygrounds.com.au info@naturaplaygrounds.com.au





le Depth

600mm

Note:

This product is designed for no softfall. Check the proposed on site softfall depth. Please adjust depts of post holes accordingly, to achieve corect overall subsurface depth. This will maintain correct height of equipment above undersurface level.

| ion - Quarterly | Comprehensive Inspection - Annually | |
|-------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| oving parts e.g. Hinks. ings. | OI plus :- Check for structural rigidity and degradation e.g. corrosion, decay etc. Where possible, remove undersurfacing to examine condition of supports and footings. | |
| | 9 | |